

## CO2 DETECTION KIT

Reference : AC 3300



**Item name** CO2 DETECTION KIT

**EAN code** 3700461410413

**Text** 1- With the engine hot, take off the radiator cap or the expansion-tub cap and put-in the indicated dose of the tracking fluid.

2- Put the bulb on the tube and squeeze it several times.

Any gas in the cooling system mixes with the tracking fluid.

The blue tracking fluid changes color (turns yellow) if there is an internal combustion fault that forces CO2 into the cooling fluid.

Conclusion: problem with the cylinder head gasket.

**Specifications**

- checks for gas combustion in the radiator
- the test fluid changes colour if a leak is detected
- fast identification of defective head gasket

**Warranty period** 2 years

**Capacity (ml)** 250.00 ml

**Capacity (l)** 0.25 l

**Tariff code** Tariff Normal (TN)

**Warranty Procedure** EASY



**\*Public price Exl. Tax : €146.00**

\*Applicable user fees from 01/09/2024 to 31/08/2025

CLAS EQUIPEMENTS  
83, chemin de la CROUZA  
73800 CHIGNIN  
France

Tel : +33 (0) 4 79 72 62 22  
Fax :

Monday to Friday - From 8 to 12h30  
and from 14h to 17h30 (16h30 on  
Friday)